SECTION VI - REACTIVITY DATA

STABILITY: Stable

HAZARDOUS POLYMERIZATION: Will not occur.

HAZE JUS DECOMPOSITION PRODUCTS:

Carpon monoxide; carbon dioxide, oxides of nitrogen, various hydrocarbon and acrid fumes.

COMDITIONS TO AVOID:

Excessive heat, poor ventilation. Corrosive atmosphere, excessive aging, sparks and open flames.